


STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

3100 Port of Benton Blvd • Richland, WA 99354 • (509) 372-7950
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

December 14, 2015

15-NWP-212

Mr. Ray J. Corey
Assistant Manager for the River and Plateau
Richland Operations Office
United States Department of Energy
PO Box 550, MSIN: A5-11
Richland, Washington 99352



Re: Letter 16-AMRP-0037, dated November 30, 2015, "Remedial Investigation Report for the 200-BP-5 Groundwater Operable Unit, DOE/RL-2009-127, Draft A and Remedial Investigation Report for the 200-PO-1 Groundwater Operable Unit Addendum 1, DOE/RL-2009-85 ADD1, Draft A"

Dear Mr. Corey:

The Department of Ecology (Ecology) approves the request for a 90-day extension to address our decision to suspend our review of the two remedial investigation reports referenced above. The new due date is January 21, 2016.

We agree that this extension will allow the United States Department of Energy – Richland Operations Office and Ecology enough time to consult on the issues related to the fate and transport modeling of potential impacts to the groundwater.

If you have any questions, please contact Cheryl Whalen, Cleanup Section Manager, at cheryl.whalen@ecy.wa.gov or (509) 372-7972, or Nina Menard, Environmental Restoration Project Manager, at nina.menard@ecy.wa.gov or (509) 372-7941.

Sincerely,

Jane A. Hedges Program Manager

Nuclear Waste Program

nm/aa

cc: See page 2

15-NWP-212

Mr. Ray J. Corey December14, 2015 Page 2

cc electronic:

Dennis Faulk, EPA Michael Cline, USDOE Jim Hansen, USDOE Margaret Clark, CH2 Jane Borghese, CHPRC Marty Doornbos, CHPRC William Faught, CHPRC Carolyn Noonan, MSA Rob Piippo, MSA Michael Turner, MSA Ken Niles, ODOE Nina Menard, Ecology Cheryl Whalen, Ecology CHPRC Correspondence Control **Environmental Portal** Hanford Facility Operating Record MSA Correspondence Control USDOE-RL Correspondence Control

cc: Rod Skeen, CTUIR
Gabriel Bohnee, NPT
Russell Jim, YN
Steve Hudson, HAB

Administrative Record: 200-BP-5 and 200-PO-1

NWP Central File NWP Reader File